## 1999 Annual Report Review

Permittee:	Andalex Resources, Inc.
Mine Name:	Centennial Project
Permit Number:	ACT/007/019
Date Report Received:	May 2, 2000 (PFO)
Assigned Reviewers:	Paul Baker, Peter Hess, Iim Smith

<u>Instructions:</u> The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

## Assignments:

Inspectors: Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.

Hydrologists: Review Water Monitoring Data, Precipitation and Climatological Data, Non-

Coal Waste

Biologists: Review Vegetation/Revegetation Success Monitoring, Raptor Survey

Engineers: Review Subsidence Monitoring Data, Annual Impoundment Certification,

Annual Overburden, Spoils, Refuse, Floor, etc.

Section to Review	Submitted	Yes	No	Findings
Cover Sheet		<u>X</u>		APEX Mine is not listed under MSHA ID numbers; cover sheet indicates that impoundment
				certifications are not included with annual report, but they are. There
AVS; Legal/Financial Update		<u>X</u>		Submitted as Appendix C; copy of Utah Dept. of Commerce report of Andalex officers and directors as of March '99 included.

1 C . C . 1	*7	4.040 foot of 720 foot I W food
Mine Sequence Map	<u>X</u> _	4,040 feet of 730 foot LW face was
		extracted during '99. Some pillar
		reduction by CM was practiced in
		A gate pillars, other coal
		production in the Aberdeen came
		from gate road, bleeder or set up
		room development. Some pillar
		development occurred in the
		Pinnacle Mine during '99.
Water Monitoring Data	_X	Except for 2 <sup>nd</sup> and 3 <sup>rd</sup> quarters at
		S18-1, no flow, no access, or
		negligible flow (no sampling) is
		reported for spring and stream
		sites. 12-1 in Alrad Canyon is not
		reported at all. (Sites 17-1 and 17-
		2 are reported but are not identified
		in the MRP.) Well #1 is reported
		as sampled all four quarters but
		there is no report for the 2 <sup>nd</sup>
		quarter: this missing report was
		included in NOV 2000-46-1-1.
Dog sinite time 0	N.	Centennial identifies collection of
Precipitation &	<u> </u>	
Climatological Data		runoff samples as a priority, with
		rain gauge records to document
		runoff or lack of runoff. The MRP
		states precipitation records are
		available, but does not clearly
		commit to regularly report data.
Non-Coal Waste report		NA
Subsidence Monitoring	<u>X</u>	Submitted report contains info
Data		relative to 20 subsidence
		monitoring points from 3 control
		points. 4 new LW monitoring
		points were established to monitor
		2000 subsidence. Mr. Bruce Ware
		indicates that neither vertical nor
		horizontal deflection has occurred
		at any of the points. The report is
		not certified by Mr. Ware.
L		1

Annual Impoundment	I	X		All quarterly inspections by Mike
Certification				Glasson included with report; P.E.
Certification				certified annual impoundment
				inspections and certifications by
				Dan Guy of Blackhawk
	}			Engineering are included; all ponds
				are maintained according to design
				and meet R645 requirements.
Annual Overburden,		X		Submission of geologic or
Spoil, Refuse, Floor, etc.				geophysical is not required by the
<b>Spon, 1101000,</b> 11001, 010.				MRP. There are no refuse piles at
				the Centennial project.
Vegetation Data			X	
	_	<u></u>		
Revegetation Success			<u>X</u>	Not required
Monitoring	<u> </u>			
Raptor Survey			_X	Not required. Andalex has been
		<del></del>		mining under the uppermost
	_			portions of Deadman Canyon and
				under the plateau where no raptor
				nests have been found and there is
				poor quality cliff habitat.
Other Information				